

PREPARATION FOR SUMMER (THE SPRING INSPECTION):

- In order to prevent obstructions your service tech will clean the inside coils, condensate pans, traps and lines.
- For efficient operation he will clean the outside coil and straighten fins.
- Many equipment manufacturers suggest that a 10% refrigerant loss will result in a 20% decrease in the efficiency of your system. So the technician will check the refrigerant levels and find the leak if they are low.